
MEAN/RMS X of Folds ; Inner M08
Scan Line Y= −50 mm
Scan Line Y= 0 mm
Scan Line Y= 50 mm
Scan Line Y= 100 mm
Scan Line Y= 150 mm
Scan Line Y= 200 mm
< X nominal − X measured > (mm.)
RMS (X nominal − X measured) (mm)
fold number